ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
DASARAHALLI

Ward No.
13

Ward Name
Mallasandra

Street ID
W0219, W0213, W0227, W0190, W0184, I0229, W0174, W

Street Name
Chowdeshwari Temple Rd, NA

Significant Landmark
Santhosh Nagara

Segment No.
13/S-W0219/S114619

Total Length (m)
21.55

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	2.90	77.519714	13.051820	77.519711	13.051794	1St Cross Ravindra Nagara	6th Cross Ravindra Nagar
2	2.47	77.519647	13.051503	77.519639	13.051483	1st Cross Ravindra Nagara	5th Cross Ravindra Nagar
3	2.95	77.519510	13.050882	77.519504	13.050855	1st 1st Cross Ravindra Nagara	3rd Cross Ravindra Nagara
4	2.95	77.519443	13.050620	77.519437	13.050594	1st Cross Ravindra Nagara	2nd Cross Ravindra Nagar
5	2.99	77.518383	13.048614	77.518407	13.048600	Pipeline Road	2nd Santhosh Nagar
6	3.90	77.517686	13.049134	77.517713	13.049110	Pipeline Road	5th Cross Santhosh Nagar
7	3.39	77.516814	13.049768	77.516841	13.049753	Pipeline Road	8th Cross Santhosh Nagar

Segment Details

Work Details

History of Road / Lane / Circles

Name of the Work
Improvments And Mantenance Of Culvert At Santhosh nagara In Ward No 13 Mallasandra Shettyhalli Sub Division

Sanctioned Estimated Amount (Rs.)
1000000

Sanctioned Year
2019

Year
2018 - 2019

Type of Work
Others

Other Work Type

Tender
Tender

Work Details

Job No. / Work Code
013-20-000010

Work Order No.
BBMP/EE/DDA/WO/421/19-20

Work Order Date
18/10/2019

Period of Extention

Zone: DASARAHALLI Ward No: 13 Ward Name: Mallasandra Street ID: W0219, W0213, W0227, W0190,

AE/Ward-13

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ಆಸ್ಪತ್ರೆ, ರಮಣಿ ಪ್ರಾಂಗರ, ಬೆಂಗಳೂರು.

Shettyhalli Sub Division

Scanned by CamScanner

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
14/01/2020	14/01/2021	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
D V Kumar		0.00
Phone No.	**E-Mail ID**	
9845187283		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		venkateshappa
Date of Inspection	**Remarks**	
20/03/2020		

Category	Image	Photo Remark
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	CE-D	08/05/2020	19/04/2020	Approved
EE	KS Athiqur Rehaman Idrus	02/04/2020	19/04/2020	Approved
AEE	H. Kumarappa	23/03/2020	19/04/2020	approved
AE	Venkateshappa	20/03/2020	19/04/2020	Photos Uploaded
AE	Venkateshappa	20/03/2020	19/04/2020	Created

Segment Start [redacted] This photo seems out of range.

Santhosh Nagaraja

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0219, W0213, W0227, W0190,

CE CE-D 08/05/2020 19/04/2020 Approved

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು [illegible]ನಗರ ಪಾಲಿಕೆ

Scanned by CamScanner